



Ultra Low K (ULK) Reflector Repair




The ULK reflectors within the AMAT or Novellus equipment are grouped around the UV lamp. They are subject to enormous thermal stress, causing the coating to come off after some time. As a consequence: reflection of the UV light and uniformity noticeably deteriorate.

Wear of Coating




amcoss Refurbishment Process for ULK Reflectors



The reflector refurbished by amcoss with regard to intensity, uniformity and operating life resembles a new one. Its reflection values are even better and more homogeneous than those of a new OEM reflector.

Ultra Low K (ULK) Reflector Repair

Reflection Comparison – new OEM vs. refurbished amcross ULK Reflector



Your advantage: you will receive equal and even better quality at a noticeably better price!